



QAP PENDANT

Quick Connect Adaptor
Field Cut Instructions

! READ AND FOLLOW ALL SAFETY INSTRUCTIONS !


Please read and save these instructions. Read carefully before using product. Protect yourself and others by observing all safety information, warnings and cautions. Failure to comply with instructions could result in personal injury and/or damage to product or property. Please retain instruction sheet for future reference.

Read completely before beginning. If you feel you do not have adequate electrical wiring experience, have this installed by a qualified licensed electrician.

All electrical connections must be in accordance with local codes, ordinances and the National Electric Code. This product operates on 12 VAC.

INSTRUCTIONS COXIAL CORD WITH PLASTIC INSULATION

TOOLS REQUIRED



WIRE CUTTER
not included



ALLEN KEY
included

1

A. Male Connector
B. Threaded Collar
C. Retainer

Remove set screw on male connector (A), save for later use. Loosen set screw on retainer (C).

2

2.1 Hold onto male connector (A) and unscrew retainer (C). 2.2 Remove male connector (A) and save for later use. Leave threaded collar (B) and retainer (C) on cord for later use.

3

Determine desired length, add 1 inch and cut with a wire cutter.

Note: 1 inch of the cord will be installed inside of quick connect adaptor.

4

4.1 On the end of cord, measure 1-1/2 inch and strip off outer plastic sleeve. 4.2 peel back the outer braided jacket to about 1 inch and trim off excess. 4.3 On the inner coaxial cord, strip off 1/8 inch plastic sleeve.

5

5.1 Twist and wrap braided jacket snugly to inner plastic sleeve, then insert coaxial cord into the base of male connector (A). 5.2 Make sure the inner coaxial cord can be seen from the male connector opening. 5.3 Insert set screw and tighten it to the male connector with provided allen key.

6

6.1 Bring up threaded collar (B) and retainer (C). 6.2 Hold onto male connector (A) and thread retainer (C) to the base of male connector (A). 6.3 Tighten set screw on retainer (C).

SAVE THESE INSTRUCTIONS



www.jescocolighting.com
support@jescocolighting.com
Tech Support: 855.592.0029

15 Harbor Park Drive
Port Washington, NY 11050
Main Line: 800.527.7796
Fax Line: 855.265.5768

219 South 6th Ave
City of Industry, CA 91746
Main Line: 855.654.0110
Fax Line: 626.333.2955

REV4
JW12022014